## **DART SERVICE BULLETIN SB16-1**

REF. TCCA STC: SH14-45 REF. FAA STC: SR03504NY REF. EASA STC: 10052022 REF. DGCA INDIA LOA: 07-09/2011-AED REF. BRASIL STC: 2015S07-16 REF. PHILLIPPINES LOA: C-16-0221 REF. CHINA VSTC: VSTC0757 REF. RUSSIA TC: CT316-A119

It has come to Dart's attention that in an emergency situation, the threads on the thru bolts that fasten the skidtube saddles to the DART Crosstubes and the threads on the MS21920-XX Clamps securing the steps and damper supports may prove to be a hazard when deploying the float system and may puncture the float bags.

The purpose of this Dart Service Bulletin is to inform operators with float systems installed in conjunction with DART D119-796-101/-201/-103/-203 Crosstubes that they must obtain and install the D119-796-015 Float Protection Kit per Dart Service Instruction DSI 9756 and reposition the MS21920-XX Clamps per Dart Service Instruction DSI 9753 as soon as possible.

В	ADD REFERENCE TO DSI 9753 (SEE PAR16-527)			ML	17.03.01
Α	NEW ISSUE (SEE PAR16-538)			AJS	16.09.20
REV.	DESCRIPTION			BY	DATE
DESIGN		AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
DRAWN		ML			
CHECKED		AJS	DRAWING NO.		REV. B
MFG. APPR.		N/A	SB16-1	•	SHEET 1 OF 1
APPROVED		HS	TITLE		SCALE
DE APPR.		DS=	SERVICE BULLETIN		NTS
DATE 17.03.01			COPYRIGHT © 2016 BY DART AEROSPACE LTD.  THIS DOCUMENT IS PRIVATE AND COMPEDENTIAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT IT IS  NOT TO BE USED FOR ANY PURPOSE OR COPED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT		

WRITTEN PERMISSION FROM DART AEROSPACE LTD.

APPROVED